

IRONBARK

As with all quality carpets, slight variation in colour may vary from dye lot to dye lot. It is recommended that this carpet be laid in accordance with AS2455. Seam Sealer must be used on all seams. Dual bond or direct stick installation is recommended. Protective chair pads are recommended under office chairs with roller casters to preserve the appearance and avoid premature wear. Professional cleaning is recommended. Construction of this carpet may involve the occurrence of shading. Certain light sources shining across the surface may emphasise the effect of shading. Shading is not a manufacturing defect and will not detract from the carpet performance. Since carpet is a textile material, a perfect pattern match on the linear pattern cannot be guaranteed.

George Low reserves the right to modify specifications subject to manufacturing variances. Manufacturing processes may necessitate specification changes without prior notice and without prejudice.

Made in Australia

| | |
|---------------------------------|---|
| Pile Fibre | 100% Resistain |
| Yarn Structure | Nylon |
| Colouration | Solution Dyed |
| Machine Gauge | 1/10 |
| Pile Height | 6.5 mm (+/-5%) |
| Width | 3.66 m |
| Tufted Pile Weight | 20 oz/yd ² . 660 g/m ² |
| Primary Backing | Woven Synthetic |
| Secondary Backing | Synthetic |
| Average Tuft Bind | Exceeds C.I.A. requirements AS2111.15 |
| Backing Bond Strength | Exceeds C.I.A. requirements AS2111.16 |
| Fire Rating | ASISO 9239.1-2003 |
| CHF Value | 4.4 kW/m ² |
| Smoke Value | 63 % min |
| Recommended Installation | Direct Stick or Dual Bonded |
| Pattern Repeat Rating | None Commercial Heavy Duty and Stairs Residential Extra Heavy Duty and Stairs |

- Warranties/Features**
- **15 Year Limited Wear**
 - **15 Year Anti Static**
 - **15 Year Stain**

George Low of Melbourne Pty Ltd

Telephone: (03) 9587 4222 Facsimile: (03) 9587 4525 www.georgelow.com.au sales@georgelow.com.au